NTSB ID: CHI00LA312

Aircraft Registration Number: N806BF

Occurrence Date: 09/14/2000

Most Critical Injury: None

Occurrence Type: Accident

Investigated By: NTSB

Location/Time

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Belleville	MI	48111	2215	EDT	
Airport Proximity: On Airport	Distance Fror	n Landing Facility:		Direction Fro	m Airport:

Aircraft Information Summary

Aircraft Manufacturer	Model/Series	Type of Aircraft
Cessna	208B	Airplane

Sightseeing Flight: No

Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

HISTORY OF FLIGHT

On September 14, 2000, about 2215 eastern daylight time, a Cessna 208B, N806BF, piloted by an airline transport pilot, sustained substantial damage to its tail section on contact with the ramp surface while standing on the ramp. The flight encountered a shift in cargo on takeoff roll, aborted its takeoff, and taxied back to the ramp at Willow Run Airport (YIP), near Belleville, Michigan, where it's tail section came to rest on the ramp following engine shutdown. The non-scheduled domestic cargo flight was operating under 14 CFR Part 135. Visual meteorological conditions prevailed at the time of the accident. The pilot was uninjured. The flight was originating at the time of the accident and was destined for Virgil I. Grissom Municipal Airport, near Bedford, Indiana.

An Air Traffic Control Tower specialist stated:

On or about September 14, 2000, I cleared a Cessna Caravan (C208) for takeoff and, while on the roll, the Caravan aborted stating that his load had shifted. (I don't recall if the aircraft needed to return to the ramp, or fixed his load on the runway). The aircraft later departed without incident.

I don't recall the aircraft callsign or the exact time or date, but I do recall that it was after dark and that the Caravan initially aborted takeoff. $\$

A Federal Aviation Administration (FAA) inspector interviewed the pilot after the accident. The inspector's record of interview stated:

[The pilot] explained that he didn't load the aircraft that someone else had while he watched. ... According to him, prior to this incident only three to four straps were used. ... [The pilot] went on to explain that the cargo shifted upon the takeoff roll. The taxi to the runway was normal but when he began the takeoff he heard a loud noise from the rear of the aircraft and looked to see the cargo pallet resting against the rear wall of the cargo compartment. ... Upon returning to the ramp he shut down the engine and that's when the aircraft fell on its tail. ... He also said that he was glad that it didn't happen after he had rotated because he was sure that he would have been a fatal accident.

A FAA inspector interviewed a witness. The inspector's record of interview stated:
... [The witness] stated that when the aircraft sat on its tail, [the
Fixed Base Operator (FBO) there] was asked to unload the cargo, which only
had one strap holding it down, the 'D' ring had come loose from the floor
attachment, and that the cargo was still on rollers under the skid.

NTSB ID: CHI00LA312

Occurrence Date: 09/14/2000

Occurrence Type: Accident

Narrative (Continued)

[The witness] stated that they initially loaded the cargo on the aircraft only, and that the pilot was the one that secured the cargo prior to the incident. After the incident [the FBO] un-loaded the cargo on request of the pilot ... and then was asked to reload the cargo by [the pilot] because the pilot stated something about a hernia. [The witness] stated that the only way they would load the cargo on the airplane again was if they loaded and secured the cargo per their procedures because when [the pilot] secured the cargo he only used one strap and left the load on the rollers. ... [The witness] stated that the plane departed the airport with the cargo about 45 minutes after the accident.

PERSONNEL INFORMATION

The pilot was an airline transport pilot. He held single, multiengine, and instrument ratings with instructor ratings in the same. He held a Second Class Medical Certificate with limitations for glasses. He reported his total flight time as 4,390 hours, total time in make and model as 75.8 hours, and 71 hours in the last 30 days.

AIRCRAFT INFORMATION

The airplane was a Cessna 208B, serial number 208B-0806. The last AAIP inspection was performed on August 29, 2000. The airplane had accumulated 29.2 hours time since its last inspection.

METEOROLOGICAL INFORMATION

At 2153, the YIP weather was: Wind 290 degrees at 8 knots; visibility 10 statute miles; sky condition clear; temperature 12 degrees C; dew point 12 degrees C; altimeter 29.91 inches of mercury.

TESTS AND RESEARCH

An FAA inspector acquired the double stud cargo tie down ring from the operator. The ring was sent to the National Transportation Safety Board Materials Laboratory for examination.

National Transportation Safety Board Materials Laboratory Factual Report number 01-069 stated:

Examination of the plunger revealed that there were portions of the pin in each end of the pin hole. The portion that would have retained the plunger over the body was missing. ...

The distance from the lowest point on the plunger pin \dots to the underside of the plunger \dots was measured and found to be 0.684 inches.

The fracture face, [of one of the roll pins], displayed a shiny granular appearance typical of a brittle fracture. ...

The side view ... illustrates the plunger in its lowest position with the pin contacting the bottom of the stud body hole In this position there is a gap of 0.09 inches between the bottom of the plunger ... and the bottom of the stud body (See appended National Transportation Safety Board Materials Laboratory Factual Report number 01-

NTSB ID: CHI00LA312

Occurrence Date: 09/14/2000

Occurrence Type: Accident

Narrative	(Continued)
-----------	-------------

069.)

ADDITIONAL	INFORMATION

The parties to the investigation included the FAA and Telair International.

The aircraft's tie down ring was returned to Thunder Aviation.

NTSB ID: CHI00LA312

Occurrence Date: 09/14/2000

TACIDAL REPORT	Occui	Occurrence Bate: 09/14/2000										
AVIATION		Occur	urrence Type: Accident									
Landing Facility/Approach Inform	nation											
Airport Name		,	Airport ID:	Airport Eleva	tion	Run	way Used	Runwa	ay Lengt	th	Runv	vay Width
Willow Run Airport			YIP	716 Ft	. MSL							
Runway Surface Type: Unknown												
Runway Surface Condition: Unknown												
Type Instrument Approach: NONE												
VFR Approach/Landing: None												
Aircraft Information												
Aircraft Manufacturer Cessna			Model 208E	l/Series B						Numbe 3-0806	er	
Airworthiness Certificate(s): Normal												
Landing Gear Type: Tricycle												
Homebuilt Aircraft? No Nu	mber of Seats: 2	2	Certifie	Certified Max Gross Wt.			8750 LBS Numbe			er of Engines: 1		: 1
Engine Type: Turbo Prop	• • • • • • • • • • • • • • • • • • • •				Engine Manufacturer: Model/Series: Pratt & Whitney PT6-114A					Rated Power: 675 HP		
- Aircraft Inspection Information												
Type of Last Inspection			Date of Las	Date of Last Inspection Time Sir			Since Last Inspection			Airfran	Airframe Total Time	
AAIP			08/29/20	08/29/2000			29 Hours				125 Hours	
- Emergency Locator Transmitter (ELT) Information											
ELT Installed? Yes	ELT Operate	ed? No			ELT A	Aided ii	n Locating Ac	cident S	Site? No)		
Owner/Operator Information												
Registered Aircraft Owner			Street Address 9 E. Loocerman Street									
Thunder Aviation Acquisition			City Dover							State	е	Zip Code 19901
			Street Address									10001
Operator of Aircraft			Same as Reg'd Aircraft Owner									
Same as Reg'd Aircraft Owner			City						State	е	Zip Code	
Operator Does Business As:			-			Op	perator Desig	nator Co	ode:			
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s): Or	-demand Air 1	Гахі										
Operating Certificate:				Operator (Certifica	te:						
Regulation Flight Conducted Under: P	art 135: Air Ta	xi & Co	mmuter									
Type of Flight Operation Conducted:												
]	FACTU	JAL REPO	ORT - AVIAT	ION							Page 2

NTSB ID: CHI00LA312

Occurrence Date: 09/14/2000

	AVIATI	ON		Occurrence	ce Type: Acc	cident		1						
First Pilot	Information													
Name						City			Sta	ate	Date of Birth	Age		
On File						On File	49							
Sex: M	Seat Occupied:	Left	Prir	ncipal Profes	sion: Civiliar	Pilot		(Certifica	te Numb	per:	•		
Certificate(s): Airlin	e Transpor	t; Flight Inst	ructor										
Airplane Ra	ating(s): Multi	-engine Lar	nd; Single-e	ngine Land										
Rotorcraft/Glider/LTA: None														
Instrument Rating(s): Airplane														
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine; Instrument Airplane														
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review? 07/10/2000														
Medical Ce	rt.: Class 2	Medica	l Cert. Status	S: Valid Med	dicalw/ wa	ivers/lim.		Date of	Last M	edical E	xam: 06/16/20	00		
		•						•						
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Night Instrument Rotorcraft C				Glider	Lighter Than Air		
Total Time		4390	76	3583	619	117	1 2	72	190					
Pilot In Con	nmand(PIC)	3967	76	3583	598	102								
Instructor		2025	0	2025	0	30	_		\rightarrow					
Last 90 Day		186	76	186	0	2:		12	0					
Last 30 Day		71	71	71	0		7							
Last 24 Ho		0	0	0	0) 	0	0	Ι.	d Pilato N			
Seatbelt Us	sed? Yes	Shou	lder Harness	Used? Yes		Tox	Toxicology Performed? No Second Pilot? No							
Flight Pla	n/Itinerary													
	ght Plan Filed: N o	one												
Departure F	Point					Sta	State Airport Identifier			Departure Time		Time Zone		
Same as	Accident/Incide	nt Location					YIP			1830		EDT		
Destination						Sta	te A	irport Ident	ifier					
Bedford		IN		FR										
Type of Cle	earance:					-	-							
Type of Air	space:													
Weather	Information													
Source of I		Service Stat	tion											
Method of	Briefing: Unkno	wn								_				
				FACTUAL	REPORT -	AVIATIO	ON					Page 3		

NTSB ID: CHI00LA312

Occurrence Date: 09/14/2000

Occurrence Type: Accident

	ETYBOR	Occurrenc	Occurrence Type: Accident									
Weather	Information											
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Distance From Accident Site					Direction From Accident Site		
YIP	1853	EDT	716 Ft.	. MSL	NM Deg. f					g. Mag.		
Sky/Lowes	st Cloud Condition: Clear				Ft. A	GL	Condition of Light: Night					
Lowest Ce	illing: None	Ft.	AGL	Visibi	ility:	10	SM	Alti	meter:	29.91	"Hg	
Temperatu	ıre: 54 °C [Dew Point:	54 °C	Wind	Direction:	290			Dei	nsity Altitude:		Ft.
Wind Spee	ed: 8		Weath	ner Condti	ions at Acc	ident S	Site: Visual C	Cond	itions			
Visibility (F	RVR): Ft.	Visibility (RV	/V)	SM	Intensity	y of Precipi	tation:					
Restrictions to Visibility: None												
Type of Precipitation: None												
Accident	Information											
Aircraft Da	mage:		Aircraft Fire	ire:				Aircraft Exp	olosio	n		
Classificati	on:											
- Injury Su	mmary Matrix	Fatal Ser	rious Mino	or	None	TOTAL						
First Pi	lot				1	1	1]					
Second	d Pilot						7					
Studen	ut Pilot						7					
Flight I	nstructor						1					
Check	Pilot						1					
Flight E	Engineer						7					
Cabin A	Attendants						7					
Other 0	Crew						7					
Passer	ngers						-					
- TOTAL A	ABOARD -				1	,	1					
Other 0	- Ground						1					
- GRANE	O TOTAL -				1	,	1					

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: CHI00LA312

Occurrence Date: 09/14/2000

Occurrence Type: Accident

							-			
/\	dm	ını	Ctr	つけい	10	Int	10ri	സവ	tιΛ	n
$\overline{}$	um	11 11	อแ	au	/ =	11111	OH	III a	แบ	ш

Investigator-In-Charge (IIC)

Edward F. Malinowski

Additional Persons Participating in This Accident/Incident Investigation:

Grant Gillian FAA Inspector FAA 10801 Pear Tree Lane St. Ann, MO 63074